



WESMINSTER PLAYGROUND LEAD WATER TEST RESULTS May 16th, 2016



| | Building Location | Sample Collected Date | Water Source ID | Device Type | Floor | Device Location | 1st Draw - Sample ID | Final Result - 1st Draw (ug/L) | 2nd Draw - Sample ID | Final Result - 2nd Draw (ug/L) | Remediation | Retest Date | Retest 1st Draw | Retest 2nd Draw |
|---|------------------------|-----------------------|-----------------|-------------|--------------|------------------------------|----------------------|--------------------------------|----------------------|--------------------------------|-------------|-------------|-----------------|-----------------|
| 1 | WESTMINSTER PLAYGROUND | 5/20/2016 | WS- 011553 | Utility | Ground Floor | Exterior In play ground area | WT-042916-11570- A | 4.5 | WT-042916-11570- B | 2.9 | | | | |

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.